

CHECKWEIGHER DATA CAPTURE SOFTWARE

Routes Checkweigher Weight Data Directly to Your Desktop Computer

ROGRAI	NI W	1 DE	MO MOD	E 98.0 - 102.	U				
Saye	Save Not saving to any file								
Print	-	Good	data received	from the checkweig	diar.				
	M	IEIGH	Т	C.P.	м.				
	1	05.0	3	9	2				
COUNT		WEIGHT		TIME	STATU				
36	122	105.03	9/11/00	IS STATISTIC AR	Ones				
-35	4	96.05	7/11/201	3 8142125 AR	and the second second				
34		\$7.08	7/11/201	3 5:42:23 AR	and the second second				
33	-	101.05	7/11/20	MA 5112128 AR	Over:				
32	14.1	103.04	. 9/11/00	13 5142122 AR	Ones				
-51	4	100.05	, 7/11/20	13 3:42:21 AM	E-mail				
30		97.97 .	7/11/201	3 5142121 AR	and the second second				
28		98.02	7/11/201	3 8142128 AR	Contract of the				
28	127	105.05	. 9/11/00	13 SIGEID AR	Onles				
1.17	14	99.18	7/11/201	3 5:42:18 AR	and the second				
16	(+)	98.09 .	7/11/201	3 5:42:19 AR	and the second sec				
25	100	B8.01 .	7/11/201	3 5:42:18 AR	and the second second				
24	141	97.0E .	7/11/201	NA BELEVER C	and the second se				
125	14	101.00	, 7/11/00	13 5:42:17 AR	E. Contraction				
22		102.01	. 7/11/20	L3 5:42:17 AM	Over				
21		97.18 .	7/11/201	NA D1:52:16 AR	1000				
10	14	98.00	7/11/201	NA DISCOUTE C	and the second				
1.9	14	102.10	, 7/11/00	13 5:42:15 AM	Over				
18	1	105.05	. 7/11/20	12 3:42:13 ML	Over.				
17	141	101.10	7/11/20	13 5:92:14 AR	in the second				
10	10	104.08	, 7/11/20	13 3:42:14 AR	Onet				
1.1	- 14	98.03 .	7/11/201	3 5:42:13 AR	Concerned in the local division of the local				
14	-	102.07	7/11/20	13 3:42:12 Aff	Over				
13	- 141	100.00	2/11/20	13 5:92:12 AR	and the second second				
12		56.08 .	7/11/201	3 3:42:11 AR					

The All-Fill Checkweigher data capture software is a PC-based utility to instantly transfer each container's weight directly to a PC. Any All-Fill Checkweigher – CW-10, EW-8, PW-12, MW-16, HP-14, HW-15 equipped with CW700 controls can be used for data capture to your PC. The Data Capture Software can connect via an ethernet connection or RS-232 connection. Older All-Fill and Alpha Checkweigher models may require a software update to use the Data Capture Software.

de la la

The software installs easily on most standard configuration PC's (see "System Requirements"). Upon installation, a screen appears to specify connection to the All-Fill Checkweigher. Once connected, a central Weight Log screen appears listing the Setup Program's Product Code, each checkweighed package, product code, time/date, and accept/over/under status. Print and save commands on this screen can specify where the weight data is recorded or listed in a printer. The save command allows data to be recorded as either ASCII text or comma delimited formats for use with other applications (i.e.., spreadsheets, databases, etc.)

A current batch report screen lists relevant weight data for the current and most recent batch. A pie chart graph on this screen provides a graphic depiction of batch weights and status. A weight graph screen displays weight trending data over time with user-selectable maximum and minimum weight limits. An alarm log screen provides a summary of any checkweigher errors by type, date, and time. The weight graph and alarm log are for display/print-ing purposes only. Data is not written to any files.

www.AllFill.com • 610 524 7350 • 418 Creamery Way, Exton, PA • info@AllFill.com


ADDITIONAL SOFTWARE FEATURES:

System Requirements: The Single Weight Data Capture software has been designed for use with any PC running the Windows platform, version PC up to Windows 7. MS Office highly recommended for use of single weight data.

Weight Log

1	DEMO MODE 98.0 - 102.0	103.08	Over	12/26/2013 9:09:50 AM
1	DEMO MODE 98.0 - 102.0	104.03	Over	12/26/2013 9:09:51 AM
1	DEMO MODE 98.0 - 102.0	100.09	Accept	12/26/2013 9:09:51 AM
1	DEMO MODE 98.0 - 102.0	104.05	Over	12/26/2013 9:09:52 AM
1	DEMO MODE 98.0 - 102.0	100.04	Accept	12/26/2013 9:09:52 AM
1	DEMO MODE 98.0 - 102.0	98.09	Accept	12/26/2013 9:09:53 AM
1	DEMO MODE 98.0 - 102.0	101.06	Accept	12/26/2013 9:09:53 AM
1	DEMO MODE 98.0 - 102.0	102.01	Over	12/26/2013 9:09:54 AM
1	DEMO MODE 98.0 - 102.0	103.03	Over	12/26/2013 9:09:54 AM
1	DEMO MODE 98.0 - 102.0	96.03	Under	12/26/2013 9:09:55 AM
1	DEMO MODE 98.0 - 102.0	105.04	Over	12/26/2013 9:09:55 AM
1	DEMO MODE 98.0 - 102.0	102.04	Over	12/26/2013 9:09:56 AM
1	DEMO MODE 98.0 - 102.0	99.04	Accept	12/26/2013 9:09:56 AM
1	DEMO MODE 98.0 - 102.0	98.03	Accept	12/26/2013 9:09:57 AM
1	DEMO MODE 98.0 - 102.0	100.07	Accept	12/26/2013 9:09:57 AM
1	DEMO MODE 98.0 - 102.0	98.07	Accept	12/26/2013 9:09:58 AM
1	DEMO MODE 98.0 - 102.0	101.07	Accept	12/26/2013 9:09:58 AM
1	DEMO MODE 98.0 - 102.0	96.01	Under	12/26/2013 9:09:59 AM
1	DEMO MODE 98.0 - 102.0	97.03	Under	12/26/2013 9:09:59 AM
1	DEMO MODE 98.0 - 102.0	99.06	Accept	12/26/2013 9:10:00 AM
1	DEMO MODE 98.0 - 102.0	98.09	Accept	12/26/2013 9:10:00 AM
1	DEMO MODE 98.0 - 102.0	104.06	Over	12/26/2013 9:10:01 AM
1	DEMO MODE 98.0 - 102.0	99.01	Accept	12/26/2013 9:10:01 AM
1	DEMO MODE 98.0 - 102.0	98.02	Accept	12/26/2013 9:10:02 AM
1	DEMO MODE 98.0 - 102.0	102.1	Over	12/26/2013 9:10:02 AM
1	DEMO MODE 98.0 - 102.0	99.03	Accept	12/26/2013 9:10:03 AM
1	DEMO MODE 98.0 - 102.0	104.02	Over	12/26/2013 9:10:03 AM
1	DEMO MODE 98.0 - 102.0	101.07	Accept	12/26/2013 9:10:04 AM
1	DEMO MODE 98.0 - 102.0	102.07	Over	12/26/2013 9:10:05 AM
1	DEMO MODE 98.0 - 102.0	104.01	Over	12/26/2013 9:10:05 AM


Weight Graph Display



Batch Report

alle:	and the second se				_10
Not paving to any life					
	Current I	Batch Report	Accept	20 C	
Start Time: 7/11/2013 5:43:17 AM					
Last Weight:	103.08	CPM.	120	1 7	
Average:	100.93	Std Dev:	1.544		
Max Wt:	103.08	Min Wt	98.04		
Total:	8	Good	5	Under	
Over:	3	Under	0		Over .
End Bate	h	Į	Print		
	Last B	atch Report		Į.	Azzapi
Start Time:	7/11/2013	5:42:06 AM			
End Time:	7/11/2013	5:43:17 AN	A		
Average:	100.32	Std Dev:	2.889		
Max Wt:	105.09	Min Wt	96.01	Unare]	
Total:	140	Good	62		Der
Over;	49	Under:	29		Total

Alarm Log



WORLD-CLASS SERVICE & SUPPORT:

We understand downtime and its effect on your bottom line. Packaging machinery is only as strong as its service and support system. If you run into challenges, All-Fill's Service team consists of 15 full time service employees with over 150 years of combined experience in the packaging industry. Our team can train, install, and troubleshoot any All-Fill machinery. We service domestically and in our international territories: Canada, Central and South America, India, China and Australia. Contact our Service team at **Service@all-fill.com.**

PARTS SUPPORT:

All-Fill machines are designed using the most innovative controls and the highest quality parts and components. All-Fill has an unmatched ability to identify and resolve issues that may arise with your machine. Our parts department provides quality support in a timely manner to reduce your downtime and stocks most parts for quick delivery. From mechanical assemblies, electronic components, tooling, machine accessories and software, we have the parts you need. Contact our Parts Department at **AFI-parts@all-fill.com.**

INTERNATIONAL INQUIRIES:

All-Fill's packaging machinery is available worldwide for almost any product and industry. Our more than 50 years of engineering expertise combined with our industry leading field support makes us a leader in the industry. We design, manufacture, install and service machinery with maximum accuracy and reliability. Our global presence means uncompromising service and support, no matter what or where your needs are. Reach out today to discuss your project with our international sales team. Contact us at **info@all-fill.com.**

www.AllFill.com • 610 524 7350 • 418 Creamery Way, Exton, PA • info@AllFill.com